

DECEMBER 20, 2001

STATEMENT OF CORRECTIVE ACTION

According to procedure, we are addressing the critical item deficiencies as requested , if further corrective statement action is necessary for the other non critical items , please advise directly to marcb@windjammer.com.

The following action has been taken to correct the deficiency as noted on the inspection conducted onboard the S/V LEGACY on December 9th , 2001 at the port of St.Thomas, USVI..

ITEMS WITH CRITICAL DESIGNATION

ITEM # 3 REF # 24 THE FINAL SANITIZING RINSE TEMPERATURE OF THE DISHWASHER RANGED FROM 121 TO 141 DEGREES. APPEARED TO NOT BE ENOUGH PRESSURE

Corrective action...low water pressure situation discussed with engineering dept onboard and agreed to increase (boost) pressure to the dishwasher to meet standard of 180 degrees for the rinse. Dishwasher operations are being monitored daily and are working as per specifications

Respectfully submitted,

Marc L. Burton
Hotel Services Dept.
1 800 542 3366