

CDC / Vessel Sanitation Program
1850 Eller Drive – Suite 1001
Ft. Lauderdale, FL 33316
USA

Dear Sir,

The following actions have been taken to correct each of the deficiencies noted during the inspection of MS-EUROPA, on Oktober 23, 2001 - at Boston

6 **POTABLE WATER**

THE HALOGEN ANALYZER-CHART RECORDER WAS NOT BEING CALIBRATED ON A DAILY BASIS.
Corrective Action taken: Halogen Analyzer Chart Recorder is calibrated daily since last inspection.

THE HALOGEN-ANALYZER CHARTS WERE NOT INITIALED ON A DAILY BASIS.
Corrective Action taken: Charts are signed daily since last inspection

17 **MAIN GALLEY - BUTCHER SHOP**

LARGER CUTS OF BEEF WERE BEING THAWED IMPROPERLY. Corrective Action
taken: Food will be thawed in future as discript in VSP under 7.3.5.1.3-1 and 7.3.5.1.3-2

19 **LIDO**

THE BREAD ROLLS ON THE BUFFET LINE WERE SUBJECT TO CONTAMINATION BY GUESTS. Corrective
Action taken: Buffet set up will be changed, bread rolls will be displayed under the sneeze guard or as recommendet in your report.

22 **LIDO BAR**

SPONGES WERE BEING UTILIZED AS PART OF THEIR FINAL SANITIZATION PROCESS
Corrective Action taken: No more sponges will be used in contact with cleaned and sanitized or in-use food-contact surfaces.

22 **MAIN GALLEY - DISHWASH**

THE WASH AND RINSE WATER TEMPERATURES ON THE WAREWASH MACHINE WERE 30 DEGREES FAHRENHEIT LESS THAN WHAT WAS REGISTERED (79 C) AND TESTED (133 F). Corrective Action taken:
Temperatures were corected during inspection, some adjustments in electronical part of the dish washer were necessary.

33 **MAIN GALLEY - PASTRY AREA**

GREASE RESIDUE WAS NOTED IN THE EXHAUST HOOD LEDGE LOCATED ABOVE THE OVENS. Corrective
Action taken: Cleaning plan has been established and for next dry dock, a plan to reconstruct the Exhaust for easy cleaning will be brought forward to the main office in Hamburg.

40 **INTEGRATED PEST MANAGEMENT**

THERE WAS NO RECORD OF TRAINING FOR THE STAFF THAT APPLY PESTICIDES ABOARD THE VESSEL. Corrective
Action taken: The training of pest – control personnel will be documented in the Pest Management Plan.

41 **HOUSEKEEPING**

PROCEDURES WERE NOT IN PLACE TO MANAGE CLEANING OPERATIONS SHOULD THE SHIP EVER REACH A 2% ATTACK RATE FOR PASSENGERS OR CREW. Corrective Action
taken: Extra precautionary cleaning measures are taken by the HK Department to prevent the spread of gastrintestinal illness from cabin to cabin.